BILL OF SUPPLY

Plot No-399, 25 Feet Road, Koushik, Enclaws, Gupta Farms Hause, Burani »

Delhi-110084 PAN: AVZPP9538N Tel.: 9871737568

Invoice No.

: 17

Dated

: 03-05-2024

Place of Supply

: Delhi (07)

Reverse Charge : N

Billed to :

APEX SCHOOL SANT NAGAR BURARI

DELHI-110084

Shipped to :

APEX SCHOOL

SANT NAGAR BURARI

DELHI-110084

GSTIN / UIN

GSTIN / UIN

FOR THE MONTH OF APRIL 2024 TO MARCH 2025

5.N.	Description of Goods	HSN/SAC Code	Qty.	Unit	Price	Amount(₹)
1.	AMC 1000 LPH RO PLANT	8421	1.00	NOS	70,000.00	70,000.00
			•			and the second s
					009/	
			10.5		1.05/1°	
			69			

Tax Rate Taxable Amt. CGST Amt. SGST Amt. Total Tax Nil Rated 70,000.00 0.00

Rupees Seventy Thousand Only

Bank Details: PUNJAB NATIONAL BANK

ACCOUNT NO-17291131001435 IFSC CODE-PUNB0172910

Terms & Conditions

E.B. O.E.

1. Goods once sold will not be taken back.

2. Interest @ 18% p.a. will be charged if the payment is not made with in the stipulated time.

3. Subject to 'Delhi' Jurisdiction only.

Receiver's Signature :

for ADITYA WATER WORKS

Authorised Signatory

DR. DEREK RICHARD MANAGER
PRINCIPAL DEREKTORANAGER PUBLIC SCHOO *(Senior Seco Sant Nagar, Burari



DEZIGN PEDIA

Contact :- +91 9711350949

Architect Interior Design

Construction

Turnkey Project

GH-6/87 Prachin Apartment, Meera Bagh Near St. Marks School, New Delhi-110087 MAIL:-dezignpedia@gmail.com Website:-dezignpedia.com

STRUCTURAL STABILITY CERTIFICATE

I personally visited <u>Apex Public School, Sant Nagar, Burari, Delhi</u> on Dated <u>19 July 2023</u>.

The school consists of three blocks.

Block-1 = Ground, First Floor and Second Floor

Block-2 = Ground, First Floor and Second Floor

Block-3 = Ground, First Floor and Second Floor

The structure of the building is based upon R.C.C. columns, beams, load bearing walls and RCC roof slab. No cracks were visible structurally. This building is structurally capable, safe and sound and can be used as a school.

It is also certified that structural design shall be/was based on National Building Code, including safety from natural hazards No structural changes should be done in the complete block structure without the advice & supervision of civil engineer.

Signature of Architect

Name of Architect

Address of Architect _____

Date :- <u>25 JULY 2023</u>

AR. VINITA VERMA CA/2021/140235 GH-6/181, Pracheen Appartment, Meera Bagh, New Delhi-110087

Signature of Structural Engineer

Name of Structural Engineer _

Address of Structural Engineer

Date :- 25 JULY 2023

SUKHVINDER SINGH Structural Consultant 8A/23G, Basement W.E.A. Karol Bagh, New Delhi-110005

MCD Licence No. SE/0359

DR. DEREKRICHARD BRENDISH,
PRINCIPAL & MANAGER About

Senior Secondary.

Senior Secondary.

Senior Secondary.